

Eaton Electronics Division 5735 W. Las Positas Blvd #100 Pleasanton, CA 94588 www.eaton.com/electronics

# **Product Change Notice**

PCN#: EE-PCN21008 04/13/2021

#### **CLASSIFICATION OF CHANGE:**

End of Life

### **DESCRIPTION OF CHANGE:**

The 1A3400-10 will be no longer manufactured. All other configurations within the 1A3400 fuse clip family will remain available and are recommended for new designs.

### **REASON FOR CHANGE:**

The 1A3400-10 has reached end of life.

## **EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:**

Both the 1A3400-10 and 1A3400-09-R have offered the same physical dimensions and circuit board pad layout, but the 1A3400-10 has a silver plating finish while the 1A3400-09-R has a tin plating finish. The 1A3400-09-R has been tested up to 30A and has acceptable heat rise per UL4248. Therefore, other than the plating finish, there will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

# PARTS FAMILIES AFFECTED:

End of Life Part Number	Recommended Replacement
BK-1A3400-10	BK-1A3400-09-R

## **TIME SCHEDULE:**

Last Time Buy Date: June 30, 2021

Last Time Shipment Date: September 30, 2021

### **SAMPLE AVAILABILITY:**

Available upon request

#### **QUALIFICATION DATA:**

Available upon request

# **ISSUED BY:**

Nick Stone

Global Product Manager - Circuit Protection

#### **CONTACT INFORMATION:**

For questions or comments, please contact your local **Eaton sales representative**.