

Before Picture


## BACKGROUND OF THIS PCN

- As we informed by the News Release on February 2, 2022, Toray industries, one of Molex's resin suppliers, announced it had improperly identified certain resin products as receiving certification from Underwriters Laboratories (UL), a global third-party safety science organization headquartered in the United States.
- https://www.toray.com/global/news/details/20220131151731.html
- As previously noted, products sold to you by Molex contain resins from Toray Industries, Inc. (collectively, the "Affected Toray Resins") that were inappropriately certified by Underwriters Laboratories (UL). Molex has since learned the Affected Toray Resins have their UL certifications revoked on March 31, 2022.
- Due to the reasons noted above, Molex has made the decision to stop shipping products that use the Affected Toray Resins as of March 8, 2022 unless an accommodation can be reached.
- This PCN is to inform you about the change from Toray resin to other UL94 V-0 resin, which we will implement to resume stable supply of these products.

After Picture

## **CHANGE OVERVIEW**

• Change a resin material for FPC 54548 series and 54550 series Housing



- Part Number Impact: 54548 series and 54550 series
  See attached impacted parts list for more detail.
- Product Impact: No impact to Form, Fit or Function.
- · Identification: We will change the Part Numbers as follows:

Contents	Current	New
Part Number	54548**33, 54548**71 54550**33, 54550**71	54548**34, 54548**72 54550**34, 54550**72
Resin	TORAY LCP UL-94 V0 (Revocation)	SUMITOMO LCP UL-94 V0

PPAP and samples available upon request



You may address inquires regarding this PCN by clicking on the below link mailto:pcn\_coordinator@molex.com?subject=PCN\_Notification:512035 or contact your Local Sales Engineer.

Note: While responding, please retain "PCN Notification: PCN Notification: 512035" in the e-mail Subject line for faster response.

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL (800) 786-6539 www.molex.com

## PCN No Part List

- 512035 0545480471
- 512035 0545480533
- 512035 0545480571
- 512035 0545480633
- 512035 <u>0545480671</u>
- 512035 0545480771
- 512035 0545480833
- 512035 0545480871
- 512035 <u>0545480971</u>
- 512035 0545481033
- 512035 0545481071
- 512035 0545481233
- 512035 0545481271
- 512035 <u>0545481371</u>
- 312033 <u>03 13 10137 1</u>
- 512035 <u>0545481433</u> 512035 <u>0545481471</u>
- 512035 <u>0545481671</u>
- 512035 0545481871
- 512055 <u>6545461671</u>
- 512035 <u>0545482033</u>
- 512035 <u>0545482071</u>
- 512035 <u>0545482271</u>
- 512035 <u>0545482471</u>
- 512035 0545482671
- 512035 <u>0545500471</u>
- 512035 0545500533
- 512035 0545500571
- 512035 <u>0545500633</u>
- 512035 <u>0545500671</u>
- 512035 <u>0545500771</u>
- 512035 <u>0545500833</u>
- 512035 <u>0545500871</u>
- 512035 <u>0545500933</u>
- 512035 <u>0545500971</u>
- 512035 <u>0545501033</u>
- 512035 <u>0545501071</u>
- $512035\ \underline{0545501233}$
- 512035 <u>0545501271</u>
- 512035 <u>0545501471</u>
- 512035 <u>0545501533</u>
- 512035 <u>0545501671</u>
- 512035 <u>0545501833</u>
- 512035 <u>0545501871</u>
- 512035 0545502033
- 512035 <u>0545502071</u>
- 512035 0545502433

512035 <u>0545502471</u> 512035 <u>0545502671</u>