

## **Product Change Notification**



Product Group: Vishay Dale/January 16, 2017/PCN-DI-317-2017 Rev 0

## **MS Series Product Obsolescence**

**DESCRIPTION OF CHANGE:** The Vishay MS21426, MS75083, MS75084, MS75085, MS18130, MS14046, MS90538, MS75101, MS75087, and MS75088 series are becoming obsolete. There is no replacement for these parts. Last time buy timeframe is provided.

**CLASSIFICATION OF CHANGE:** Product Obsolescence

REASON FOR CHANGE: The MS series have limited sales and new technology has replaced these

types of parts.

EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE: N/A

**PRODUCT CATAGORY: Inductors** 

PART NUMBERS/SERIES/FAMILIES AFFECTED: MS21426\* MS75083\* MS75084\* MS75085\*

MS18130\* MS14046\* MS90538\* MS75101\* MS75087\*

MS75088\*

VISHAY BRAND(s): Vishay Dale

TIME SCHEDULE:

Start Shipment Date: N/A Last Time Buy Date: 7/1/2017

Last Time Shipment Date: 12/29/2017

**SAMPLE AVAILABILITY: N/A** 

**PRODUCT IDENTIFICATION: N/A** 

**QUALIFICATION DATA: N/A** 

This PCN is considered approved, without further notification, unless we receive specific customer concerns or as specified by contract.

ISSUED BY: Doug Lillie, Sr. Product Marketing Manager

For further information, please contact your regional Vishay office.

## **CONTACT INFORMATION:**

The Americas

Vishay Intertechnology, Inc 1505 East Highway 50 P. O. Box 180

Yankton, South Dakota 57078

Ph: 1 605-665-9301 Fax: 1 605-665-1627 doug.lillie@vishay.com Europe

Vishay Electronic GmbH Dr.-Felix-Zandman-Platz 1 95100 Selb

Germany

Ph: 49-9287-71-2282 Fax: 49-9287-71-2496 jens.walther@vishay.com Asia

Vishay Asia Pte Ltd. 25 Tampines Street 92 Keppel Building #02-00 Singapore 528877 Ph: +65-788-6668 Fax: +65-788-3383 victor.goh@vishay.com

Vishay Intertechnology, Inc.