

Before Picture

 Change of packaging delivery unit and standard quantity needed regarding Molex terminal block part number's 391002510, 391002511 and 391002512



After Picture

Overview

- Molex must update the carton volume quantity for each of part number's 391002510, 391002511 and 391002512
- Product Impact
 - No impact to form, fit or function of the products in question.
 - No impact to the carton type and packaging method. It is only a change to the quantity in the packaging.
- Part Number Impact
 - See attached impact list



You may address inquires regarding this PCN by clicking on the below link mailto:pcn_coordinator@molex.com?subject=PCN_Notification:513316 or contact your Local Sales Engineer.

Note: While responding, please retain "PCN Notification: PCN Notification: 513316" in the e-mail Subject line for faster response.

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL (800) 786-6539 www.molex.com

	Current	Current		Jew Standard	New Minimum
Molex Part Number	Standard Pack	Minimum Order Quantity(MLQ)	_	Pack Quantity (DU)	Order Quantity(MLQ)
391002510	125	375		250	500
391002511	125	375		250	500
391002512	125	375		250	500