

Product/Process Change Notifications

PCN - 17 021



Release Date: April 26 2017

| | | | |
|-----------------------------------|---|----|------|
| Product Name: | Millipacs | | |
| | Millipacs 5 Row Right Angle Header | | |
| Product Manager: | Verghese John | | |
| Subject: | Notification of Planned Change | | |
| Distribution: | Global | | |
| Type of Change: | Design Change | | |
| Change Description: | Removal of End Ribs in Millipacs Right Angle Header Connector | | |
| Reason for Change: | Continuous improvement in product to avoid possibility of rib breakage. Functionally this rib does not have any impact on the product | | |
| Affected Parts: | See attached affected parts list | | |
| Effective Date of Change: | July 31, 2017 | | |
| Last Time Buy Date: | NA | | |
| Last Disty Return Date: | NA | | |
| Last Time Shipment Date | NA | | |
| Datasheet Attached? | No | | |
| Qual/Test Data Attached? | No | | |
| Samples Availability Date: | July | 31 | 2017 |
| Available Alternatives? | Select | | |
| Questions? | <i>Contact your local AFCI Representative, or Product Manager</i> | | |
| | <i>Verghese John</i> | | |
| | <i>Tel: +91 484 4090814 / email: verghese.john@fci.com</i> | | |

Note:

Customers should contact Product Manager (or their local AFCI Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .